


# Field Assembled Transition (Anode) Risers with LYCOFIT® Connection



## Benefits

- No fusion equipment required.
- Fast and easy connection - fully installs in 3 minutes or less.
- No fittings to purchase - each riser includes a LYCOFIT compression sleeve that attaches to a factory-welded barbed spigot.
- Available in sizes from 3/4 IPS through 2 IPS
- No special prep needed on PE pipe.

## Fast and Easy Installation



Typical Installation Procedures	Standard Transition Risers	Lyall Field Assembled Risers
Expensive/Heavy Fusion Equipment Needed	Yes	<b>No</b>
Power Source For Installation Tools	Yes	<b>No</b>
Socket Fusion Fittings/Butt Fusion Required	Sometimes	<b>No</b>
PE Pipe Needs Special Preparation Before Installation	Yes	<b>No</b>
Chance for First Attempt Leaks (Rework Required)	Sometimes	<b>Never</b>
Tools Require Special Cleaning/Maintenance	Yes	<b>No</b>
Typical Time For Installing Traditional Riser	20 Minutes	<b>3 Minutes</b>

LIT-FARLCDS-121214

CUSTOMER SERVICE | (800) 535-9255 | RWLyall.com

